

GUIDE FOR PHOTOGRAPHING DEFECTIVE PRODUCTS.

1. PRODUCT ID

Product IDs are found on the label on the length and door panel. The product ID number is underlined in red.

You can also find Product IDs (Pos nr) on the order confirmation or invoice.



2. DOOR OVERVIEW

In the overview, it's necessary to get an idea of what the product looks like and where it is installed.



3. PHOTOGRAPHING DEFECT ON THE DOOR

Photograph the defect in a way that it remains fully visible in the picture.



4. EVALUATING GLASS DEFECTS


Glass defects are assessed from a distance of 2 meters and perpendicular to the surface of the glass. Evaluation should be done without direct sunlight and artificial light (for example, on a cloudy day).

5. MEASURING DOOR PANEL CURVATURE

When measuring the curvature of the door panel, take the first picture showing the measurement method.

Both ends of the measuring rods must be against the product.

Do not measure from the wrong side! Both ends of the measuring rods must be against the product.



The permitted curvature of the door panel is 2 mm per meter.